



Billy Laue found these directions on the GWRRRA webpage under the technical tips. I felt they would become handy for future time adjustments (day light savings, etc). Tom Sprague.

Adjust Your Gold Wing Navi For Daylight Savings, Here's How

Don't forget that Daylight Savings Time is coming early this year. Direct from Honda, here's how to adjust your Navi satellite equipped GL1800 Gold Wing for the early time change.

Due to the 2005 Energy Policy Act, Daylight Saving Time for 2007 begins on Sunday, March 11 – three weeks earlier than last year. The GL1800 Navi receiving unit features an automatic Daylight Saving feature that was programmed for the old dates. To correct for the time change, do the following:

1. Turn the key ON – if the Navi display does not appear, press the DISP button.
2. Press ENT to start the Navi system.
3. Select MENU, then select Main Menu.
4. Select Setup/Info, and press ENT.
5. Select Setup/System, and press ENT.
6. Select either 1 or 2, and press ENT.
7. Toggle to Daylight Saving, select YES, and press ENT. This will automatically advance the time one hour.

NOTE: Selecting NO turns the automatic feature completely OFF.

8. Select DONE, and press ENT. Verify that the time is correct.

You will also need to manually reset the clock when Daylight Saving Time changes again on November 4 – one week later than before. Follow steps 1 thru 6 above, but in step 7 you will need to select NO or AUTO, and press ENT. This will automatically set the Navi system clock back one hour.